

## **SAFETY RECALL ON WEAVER COUGAR SADDLE BRIDGES**

Weaver Leather announced that the **solid black** rope bridge included with Cougar harnesses sold between January 2010 and August 2010 may not be suitable for use and should be taken out of service. **Discontinue use of this product immediately!** This request is being made due to a recent incident involving the failure of one such rope bridge that did not result in injury.

Please note that this notice DOES NOT APPLY to **yellow and black striped** rope bridges made prior to 2010.

Item numbers affected include:

SherrillTree item numbers for saddle and bridge; COU-(+size) and 33525SO  
Weaver's item numbers are 08-01075 (+size) and 08-01076 (+size)

In anticipation of a sizeable return, (Weaver reports about 1,200 units sold) SherrillTree has requested as many replacement units as possible until the recall is finalized. We plan to incrementally inspect and break-test incoming material to assure quality.

To keep this process as simple as possible for all, we request the following:

-Cut the (black) rope bridge from your Cougar saddle and mail the bridge along with a signed Weaver Leather Rope Bridge Acknowledgement Form (see attachment) and return shipping address to:

SherrillTree  
c/o Weaver bridge recall  
200 Seneca Road  
Greensboro, NC 27406

Or

e-mail a photograph of the cut rope bridge to [WeaverRecall@SherrillTree.com](mailto:WeaverRecall@SherrillTree.com)

-Replacements will be shipped FREE OF CHARGE on a first-come, first-served basis

-For those who send the cut bridge by mail, we have authorized a \$10 dollar credit for your trouble (end users only, 1 credit per shipment)

### **NOTES:**

This recall DOES NOT apply to rope bridges colored yellow and black.

Please DO NOT send your entire saddle as only the rope bridge itself will be replaced.

We will assist anyone with the problem, you DO NOT have to have purchased the Cougar saddle from SherrillTree.

Details of this recall are subject to change without notice.

With the exception of customer credits, this recall is the responsibility of Weaver Leather. Please visit [www.sherrilltree.com](http://www.sherrilltree.com) for additional recall notices from Weaver Leather and Anchor Bridge.

If you have any questions please contact the SherrillTree Customer Service staff at 800-525-8873.